

Appleby-Frodingham Steel Co., Ltd., Scunthorpe, Lincs.

6079

Customer North Eastern Marine Eng'g Co Ltd Date 28/5/37
 Builder Willington Quay on Tyne
 Mark or Job No. Engine No 294 (Ben) Boulton
 Customer's Order No. B1/23
 Works Order No. 2/4/35

REQUIREMENTS

TENSILE—Tons per sq. inch. 29/53
 ELONGATION—per cent.
 CONTRACTION OF AREA—per cent.
 ELASTIC LIMIT—
 per sq. inch or per cent.


Batch No.
 Inspection Reynolds

We hereby certify that the material described below has been made by the Open Hearth process, and is that which has been satisfactorily tested in the presence of the Surveyor, in accordance with the rules of Lloyd's Register.

Initials of Test House Manager H.W.S.

THE UNITED
 STEEL
 COMPANIES LTD

PLATE No.	CAST MARK	POSITION	PLATE MARK	PIECES CUT	SIZE	THICK-NESS	APPROX. WEIGHT				REMARKS
							T.	c.	qr.	lbs.	
B 915	40139			2	8.7 1/2 x 14 1/4	5 1/16		8	1	24 12	Rep loc
Replaces plates No B657 Cast No 39348 Shown on Hull Sheet No 1642 7/4/37 6/72											



© 2020

Lloyd's Register
 Foundation W249-0072