

"KINGSWOOD".
=====


P.Pr.824.

This case is stated in endorsements dated the 4th January, 1937 etc.,

The Adelaide Surveyor who was joined by Mr. McCowan from Sydney, now reports that temporary repairs have been effected with a view to the vessel being towed to this country.

Two Donkey Boilers have been placed on board, temporary repairs effected to broken pumping connections and the necessary feed pumps and feed tanks ~~repaired~~ ^{fitted}, ~~starting~~ ^{steering} gear overhauled and some temporary electric light wiring installed.

The Donkey Boilers referred to were not constructed under survey, but have been supplied with Government Certificates. It is submitted action be deferred.


21.6.37.

W249-0127



© 2020

Lloyd's Register
Foundation