

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

(Report on Vessel No. 95796

Port

hwr

SHIP FORGINGS OR CASTINGS.

to report that the undermentioned ~~Iron or Steel Forgings or~~
manufactured by *Messrs E. Jopling & Son Ltd*
Sunderland for the Vessel No. *38 Kingswood*, being ^{REPAIR} ~~built~~
of

inspected by me as set forth below and found to be, so far as can
be ascertained.

Castings has been despatched to
Messrs Donkin & Co. Ltd. Walkergate.

D.E. Galleford.

1 TILLER

Sunderland
14. 8. 37

STERN FRAME.

RUDDER FRAME.

STEM

Steel Casting
Electric Furnace
Heat treated
as per pattern
Rough dressed.
13/8/1937

Test n° 222

31.2

✓

32

✓

120°

✓

8 ft

✓

yes

OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

chargeable) £ *Monthly a/c*
at

whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

W249-6177

© 2020 *15. 3. 17*

Repair

Lloyd's Register
Foundation

Handwritten notes in Chinese script, likely bleed-through from the reverse side of the page.

1841

32
 31
 30
 29
 28
 27
 26
 25
 24
 23
 22
 21
 20
 19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1

$\frac{w}{a}$ $\frac{w}{a}$ $\frac{1}{100}$ $\frac{1}{100}$

© 2020

Lloyd's Register
Foundation

29

Thompson
TILLER

(if any
To be pa
Iron. state

Iron. state