

th February 1937



DIAGRAM RECEIVED FROM LLOYD'S REGISTER OF SHIPPING, LONDON:-

INGSWOOD OWNERS HAVE DECIDED TOW VESSEL WITHOUT CARGO TO THE RIVER  
NE FOR PERMANENT REPAIRS STOP OWNERS DESIRE TEMPORARY REPAIRS FOR  
YAGE HOME SHOULD BE MINIMUM AND IT IS AGREED THAT BOILER ROOM  
TERTIGHT BULKHEAD AND WATERTIGHT BULKHEAD BETWEEN HOLDS NOS. 1 & 2  
ED NOT BE DEALT WITH FOR VOYAGE PROVIDED REPAIR OR RENEWAL OF  
LLISION BULKHEAD AND TEMPORARY REPAIRS DETAILED YOUR SPECIFICATION  
RIED OUT TO YOUR ENTIRE SATISFACTION."

DIAGRAM REPLY TO LONDON 17/2/37.

INGSWOOD REFERRING TO YOUR CABLE OF 16TH FEBRUARY ARRANGEMENTS  
E BEING MADE ACCORDINGLY"



© 2020

Lloyd's Register  
Foundation

W249-0195