

"KINGSWOOD"
=====

The Sydney Surveyors have now forwarded some photographs of the damaged boiler and of the structural damage to the ship due to the explosion.


The front tube plate of the boiler is bulged outwards and most of the tubes have been forced out of the boiler, some of them being found in the aftermost crank pit.

Mr. McCowan states that further information and reports will be ~~found~~ ^{forwarded} later.

The cause of the explosion is not yet determined.

It is submitted further information be awaited and that Mr. McCowan be asked to state whether the tubes were found to be in a wasted condition and whether the screw threads of the stay tubes were good.

12
W
S.D. 3.2.37. at



© 2020

Lloyd's Register
Foundation

W249-0214