

COPY.

DLT MCCOWAN

(12.1.37)

CARE MIRAMAR


SYDNEYNSW

WOOD OWNERS MOST ANXIOUS THAT SPECIFICATION COMPLETE  
DETAILS AND COVERS VESSEL BEING REPAIRED TO PLACE HER  
ICAL CONDITION AS PRIOR ACCIDENT ALSO THAT REPAIRS LEAVE  
PHOLE FOR PATCHED JOB TELEGRAPH CONFIRMATION SO THAT  
SATISFY OWNERS STOP IS FORMAL INVESTIGATION BEING HELD  
CAUSE EXPLOSION STOP WAS EXPLOSION INTERNAL OR EXTERNAL  
LER ALSO INDICATE EXTENT ACTUAL BOILER DAMAGE

COMMITTEE

© 2020

6407



Lloyd's Register  
Foundation  
W249-0233