

S.S. "KINGSWOOD".

Messrs. Joseph Constantine S.S. Line Ltd., Owners of the above vessel, telephoned this morning to say that the auxiliary boiler of this vessel had burst at Port Pirie, and that very serious damage had been occasioned thereby to engines, bulkheads, etc., so much so that the vessel appeared to be wrecked internally.

In the circumstances they asked that the best Surveyor on the Australian Staff available, should be at once sent to Port Pirie, with a view to reporting as to the damage and the possibility of repairs as soon as possible.

4.1.37.

IT IS SUBMITTED Mr. A.J. McCowan, Principal Surveyor for Australia and New Zealand, be informed and requested to arrange for an experienced Ship & Engineer Surveyor to join Mr. A.J. Elms in the survey.

4.1.37.



Lloyd's Register
Foundation

W249-0260