

1m.12.15.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

4.7.16

VESSEL'S NAME

St. S. S. Louis

Botha Rpt.

Hul.

No. 29407

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

35.4

Depth "d"

17.45

Framing: Table No.

3 pag 10

Description

Single angle as app.

Longitudinal No.

4143

Proportions

Length =
Depth =

8.6

Deck Sheerstrake

.56

instead of

.34

as required

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

:- 100 A.1. Steel Steam Trawler as recommended.

:- 100 A.1. (Stl.) Steam Trawler.

1 BK

BK 7 1/2 4 BH. Com. Logos a 161 Q 61 F 16



© 2020

Lloyd's Register Foundation

W 250 0120