

Is it drawn and examined? no Is it fitted with continuous liner? no

Is an appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Is it fitted with continuous liner? no If so, state reasons no

5 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

Leopold viller

Rpt. Art No. 18753

Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points of the endorsement." - Extract from Sub-Committee's Report, 24/5/93.

~~DAMAGE & WEAR AND TEAR.~~

is effected to No 1 fore & Star. oil fuel tank
arrangement in accordance with the Rules & approved
tested & found in order

submitted the vessel is eligible to remain as classed with out.

Survey as recommended.

report for notation



2019

4. 5. 33

Lloyd's Register Foundation

W251-0030

1st and 2nd fuel oil tanks