

COPY.

Lloyd's Register of Shipping.



Port of ANTWERP.

2nd September 1929.

F. L. Rabey

SURVEYOR TO LLOYD'S REGISTER.

This is to Certify that

FRANK L. RABEY,

the undersigned Surveyor to this Society did at the request of the Soc. An. John Cockerill of Hoboken survey the twin S/S "LEOPOLDVILLE" No. 623 yard number on the 7th September 1928 whilst the vessel was at the yard during construction and on the 22nd July 1929 whilst the vessel was in the No. 7 city dry dock at Antwerp for the purpose of ascertaining the nature & extent of the damage stated to have been caused by:-

- 1) Propeller shaft marked F.L.R. 746 having dropped owing to sling breaking when lifting the shaft on to the vessel.
- 2nd) Starboard propeller striking mooring chain whilst trying engines at the yard at Hoboken.

Upon making examination.

FOUND

RECOMMENDED

1st Damage.

Propeller shaft liner badly cut Liner to be removed, shaft to be and grooved in way of neck bush, examined in the lathe and a new liner to be fitted.

2nd Damage.

The 3 bronze blades of the starboard propeller slightly bent & fractured at the tips.

The tips of the 3 propeller blades to be dressed up.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



"LEOPOLDVILLE"

ALSO RECOMMENDED the whole of the work to be carried out so as to replace the vessel in the same good & efficient condition as she was in before the alleged damages were sustained.

THE TAX & EXP. FRB. 964.60

J. L. Rabey

SURVEYOR TO LLOYD'S REGISTER.
ANTWERP.

This is to Certify that...

...to the Committee of Lloyd's Register, stating that all repairs...

J. L. Rabey



© 2019

Lloyd's Register Foundation

W251-0152 (2/2)