

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "MARIA KYRIAKIDES" Report Rs No. 4131**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

✱ 100-A-1. (Steel)

1 Dk (Steel)

Cell IB 196' 389t, FPT 120t, APT 75t

FK, ABH, Cen, Lloyd's Av CP, B52' F27'

M

3-6-21

It is concluded the deck plating is increased in way of the openings as approved but the Surveyors should be requested to state if this is so and whether they are correct in reporting the spacing of the frame rivets as 6 1/4" in view of the frame spacing being 6 1/2".



Lloyd's Register Foundation

U253 - 0109

EAMS, Poop Deck, Angle, Bulb Angle, Plate,

Tee Bulb, or Channel

Angles on upper edge

Bridge Deck, String

Angle on ditto