

2m.431.

5E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

25 JAN 1935

SEL'S NAME

May Pemberton.

Rpt.

Ann.

No.

1675

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

~~DAMAGE & WEAR AND TEAR.~~Alterations.

ure of Survey

A steam dome fitted to the boiler
superheater fitted
H.P. cylinder liners renewed.

Screw shaft survey due 7.34. To be
held next month. Approved.

It is submitted the vessel is eligible to remain as classed with out
record of Survey as recommended.

[Signature]
25/1/35



© 2020

Lloyd's Register
Foundation

W 253-0132