

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "OCEAN CRUSADER" Report N.Yk. No. 43159

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due.....

This is a sister vessel to the "OCEAN LIBERTY" etc.

The scantlings are suitable for a draught of about 18 $\frac{1}{2}$ " in excess of that corresponding to the freeboard which could be assigned as a C.S.S. vessel.

①00A1 "With freeboard"

2 Dks. "Electrically Welded"

Cell DB 363' 1310t, DTa 20' 734t, FPT 124t, APT 166t

FK, 7BH (Cell to W dk, 6 to 2nd dk) 6 divisional W.T. BHs in 'tween dks.,
pt. Cem., Lloyd's A & CP

O.L. 441.5'

E.S.D.

a †

The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L: (A bower anchor and 45 fathoms of chain cable to be supplied).

SJA *6/11/16*
16.2.43

✓

It is concluded that the number and position of the Divisional W.T. Bulkheads in the 'tween decks are as in the previous sister vessels.

yes
8-4-43
(VESSEL SUNK)



© 2019
S.S. N.Yk

3-3-43

Lloyd's Register Foundation

W254-0007