

8 NOV 1943

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "ROHNA" REPORT Alx. No. 2608

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 2nd S.S. No.1 became due 3.43.

The class is subject to permanent repairs to indented shell plate No.1 from aft in 5th strake below sheer (ss.) at the Owners' convenience and to (a bower anchor being supplied).

The ALEXANDRIA Surveyors report (6.43) the vessel placed on floating dock and bottom coated. Shell plating in G, H, J, K & L strakes (p & s) found indented. The Surveyors recommend repairs at the first convenient opportunity.

It is submitted the vessel is eligible to remain as classed with record of docking date 6.43, subject as recommended and as above.

As now, subject.

(Docking date)
6.43.

Wals
29.10.43



© 2019

Lloyd's Register
Foundation

W258-0225