

2m, 5, 19.

1

W26-0052

Sent to Chief Surveyors

Received from Chief Surveyors

ESEL'S NAME STEEL S.S. "DROMORE CASTLE" Report Gyk.

No. 17572.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SUPERVISOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/92.)

State of Survey

When due

The Downlock Pump has been dispensed with for the present. But it is concluded the owners are agreeable to fit same when requested.

\* 100 A.1. (steel)

2 Dks (steel) & 3<sup>rd</sup> Dk (steel) in N<sup>o</sup>1 Hold.

Cell DB 340' 1051t.

FPT 132t. APT 220t.

FK. 7BH. phcam. Daydis A+CP.

P50', B113', F39

B' Type Standard except for 3<sup>rd</sup> Dk

© 2021 Lloyd's Register  
Mars  
8/12/19  
not attached