

56,8,12.

Raymond

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

26/7/13
H. H. Glenmora

Rpt. Hie

No. 26523

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

31.25

Depth "d"

8.59

Framing: Table No.

Page 3

Description

Single angle

Longitudinal No.

3060

Proportions

Length
Depth

= 11.48

Sheerstrake

as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A.1. (Std.) as recommended.

\pm 100A.1. (Std.)

1st (Std) 'Muldut'

W/B. F.P.T. 226

BK 6" 3BH beam. Lloyd's A+B Q39 87' F19

Mch. Aft



© 2020

Lloyd's Register
Foundation

BEAMS, Third and Fourth Deck, Single Angle,
Bulb Angle, Plate, Tee Bulb, or Channel
Angles on upper edge

W260-0114

Angle on ditto