

Messrs. J.L.Thompson & Sons' Yard No. 588.  
-----

Mr. Cyril Thompson has called at this Office regarding the equipment number of this vessel, which was proposed by them on the midship section as 43266 (letter c†). In computing this number they included, in error, the after deckhouses, none of which exceeds in length or breadth half the breadth of the vessel, and therefore, in the terms of Section 39, Paragraph 2(c), need not be included in the number.

Omitting these deckhouses the equipment is 43184, corresponding to letter b†, Table 53.

The matter has been carefully examined, and Mr. Thompson's revised computation is concurred in.

It is submitted the Sunderland Surveyors be informed as above, and that the equipment may be in accordance with letter b†.

It is further submitted the Surveyors be informed by wire as follows :-

"EQUIPMENT MAY BE ACCORDANCE LETTER B DAGGER WRITING".

*Ed. Mr. 28.2.39*

  
28. 2. 39.



© 2019

Lloyd's Register  
Foundation

W261-0234