

of "Wellpark"

This vessel's machinery has been constructed & fitted on board under Special Survey, & is now satisfactorily reported upon, with the exception, that the tank injection pipe, (which appears to have been too short & has been lengthened by a new end piece with leaded joint,) is objected to by the Owners Superintendent & the Surveyors.

The Surveyors recommend that this pipe should be renewed at the Owners' convenience.

It is submitted that this vessel is eligible for THE RECORD. + LMC 5.18. subject to a new tank injection pipe being fitted at the Owners' convenience.



© 2019

Lloyd's Register
Foundation

W263-0103