

V.

24 APR 1944

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "TULAGI" REPORT Syd. No. 19527

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to 15 fathoms of  $1\frac{1}{2}$ " Tayco chain cable being supplied at the first opportunity.

The SYDNEY N.S.W. Surveyors report this vessel afloat and 15 fathoms of  $1\frac{1}{2}$ " Tayco chain cable verified with certificate, now on board.

IT IS SUBMITTED the vessel is worthy to remain as classed without condition regarding 15 fathoms of  $1\frac{1}{2}$ " Tayco chain cable.

As now, without.

J.F.

19.4.44



© 2020

 Lloyd's Register  
Foundation

W266-0050