

624
624

Compulsory

Rpt. 12.

22983.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office)

Port Sunderland
 Vessel's Name North Pacific
 Official No. _____ No. in Reg. Book _____
 Port of Registry (For Foreign Vessels) _____
 Iron or Steel Steel State whether Classed by Lloyd's Register Y¹⁰
 Name of Owners Pacific Shipping Co^a Date of Verification 5th May, 1913.

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	2	ft.	8	ins.
From centre of disc to top of statutory deck line } at awning or part-awning deck }		ft.		ins.
Fresh water line above centre of disc			6	ins.
Indian Summer line above centre of disc			5	ins.
Winter line below centre of disc			5	ins.
Winter North Atlantic line below centre of disc				ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	}	at <u>main, spar or</u> upper dk.		$\frac{3}{14}$ ins.
		at awning or pt.-awning dk.		ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

Signed R.M. McFarren Surveyor.

(To be filled up in London Office.)

Statement No. 22983 Date of Committee's Minute 30.4.13
 Moulded Depth for record 25 ft. 4 ins.
 Freeboards compared and found correct by _____ date 6.5.13
 Is fee paid? new vessel Form for Certificate A © 2021
 Instructions _____ date _____
 Certificate written _____ Noted for posting _____

*Classification 1000A shelter Deck
 Conditional on the above freeboards.*



Lloyd's Register
 Foundation
 W268-0124