

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME FRANCISZKA now FORCE Report See No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

State of Survey

Condition

When due

17th 47621 (2.37)
+ day 1867
(6.39)

Subject to the mizzen mast being renewed before the end of
December this year & its redner (see repair 11.38) being
specially examined at the next dry docking

Self. 17.11.39

PLAYING TO BE DRILLED ACTION to
be carried out 24 years old not
for at next Special Survey to be
thereafter.

© 2019

Lloyd's Register
Foundation

W271-0169