

of Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_


S NAME "LA" CORDILLERA" Report Gls. No. 65664

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Survey Docking When due

Subject to permanent repairs to buckled  
shell and deck plating, frames, beams, bulkheads etc. in  
way of No.2 hold and 'tween decks (p & s) at the first  
opportunity.



W276-0008