

REPORT ON ELECTRICAL EQUIPMENT.

(OTHER THAN FOR THE PROPULSION OF THE VESSEL)

30 DEC 1942

Received at London Office.....

Date of writing Report... Sept. 30 1942 When handed in at Local Office... Oct. 5 1942 Port of... QUEBEC, P. Q.No. in Survey held at... Lauzon, P. Q. Date, First Survey... 5th Jan. Last Survey... 25th Sept. 1942
Reg. Book. (Number of Visits... 41)on the Single Screw Steamer "JASPER PARK" Tons { Gross... 7128.56
Net... 4243.69Built at... Lauzon, P. Q. By whom built... Davie Shipbldg. & Rpg. Co. Ltd. Yard No. 537 When built... 1942Owners... Waritime Merchant Shipping Ltd. Port belonging to... MontrealElectrical Installation fitted by... Davie Shipbuilding & Repairing Co. Ltd. Contract No. 537 When fitted... 1942Is vessel fitted for carrying Petroleum in bulk... No Is vessel equipped with D.F. Yes E.S.D. Yes Gy.C. - Sub.Sig. -Have plans been submitted and approved... Yes System of Distribution... 2 wire D.C. Voltage of supply for Lighting... 110Heating... - Power... - Direct or Alternating Current, Lighting... D.C. Power... - If Alternating Current state periodicity... - Prime Movers,has the governing been tested and found as per Rule when full load is suddenly thrown on and off... Yes Are turbine emergency governors fitted with atrip switch as per Rule... - Generators, are they compound wound... Yes, are they level compounded under working conditions... Yes,if not compound wound state distance between generators... - and from switchboard... - Where more than one generator is fitted are theyarranged to run in parallel... No, are shunt field regulators provided... Yes Is the compound winding connected to the negative or positive poleNegative Have machines over 100 kw. been inspected by the Surveyors during manufacture and testing... - Have certificates oftest for machines under 100 kw. been supplied... Yes and the results found as per rule... Yes Are the lubricating arrangements and the constructionof the generators as per rule... Yes Position of Generators... Both fitted on starb'd side in Engine Roomis the ventilation in way of generators satisfactory... Yes are they clear of inflammable material... Yes, if situatednear unprotected combustible material state distance from same horizontally... - and vertically... -, are the generators protected from mechanicalinjury and damage from water, steam and oil... Yes, are the bedplates and frames earthed... Yes and the prime movers and generators in metalliccontact... Yes Switchboards, where are main switchboards placed... Starb'd side in Engine Roomare they in accessible positions, free from inflammable gases and acid fumes... Yes, are they protected from mechanical injury and damage from water, steamand oil... Yes, if situated near unprotected combustible material state distance from same horizontally... - and vertically... -, what insulationmaterial is used for the panels... Ebony asbestos 3/4" thick, if of synthetic insulating material is it an Approved Type... -, if ofsemi-insulating material (slate or marble) are all conducting parts insulated therefrom as per Rule... - Is the frame effectually earthed... YesIs the construction as per Rule... Yes, including accessibility of parts... Yes, absence of fuses on the back of the board... None, individual fusesto pilot and earth lamps, voltmeters, etc... Yes locking of screws and nuts... Yes, labelling of apparatus and fuses... Yes, fuses on the "dead"side of switches... Yes Description of Main Switchgear for each generator and arrangement of equaliser switches... One 200 amp. quickbreak double pole single throw switch.and for each outgoing circuit... Two 60 amp. and one 30 amp. fused quick break D.P.D.T. switches each boardfor'd board one 200 amp. aft board one 100 amp. fused QB. D.P.D.T. quick break switchesAre compartments containing switchboards composed of fire-resisting material or lined as per Rule... - Instruments on main switchboard... 2ammeters... 2 voltmeters... - synchronising devices. For compound machines in parallel is the ammeter connected on the pole opposite to theequaliser connection... - Earth Testing, state means provided... Earth lampsSwitches, Circuit Breakers and Fuses, are they as per Rule... Yes, are the fuses an approved type... Yes, are all fuses labelled asper Rule... Yes If circuit breakers are provided for the generators, at what overload current did they open when tested... -, are the reversed currentprotection devices connected on the pole opposite to the equaliser connection... -, have they been tested under working conditions, and at what currentdid they operate... - Joint Boxes, Section Boards and Distribution Boards, is the construction and position as per Rule... YesCables, are they insulated and protected as per the appropriate Tables of the Rules... Yes, if otherwise than as per Rule are they of an approved type... -,state maximum fall of pressure between bus bars and any point under maximum load... -, are the ends of all cables having a sectional area of 0.04square inch and above provided with soldering sockets... Yes Are paper insulated and varnished cambric insulated cables sealed at the ends... None fitted

and found satisfactory.....**Yes**

The Electrical Equipment is installed in accordance with the approved plans and the requirements of the Rules.
All Insulated Conductors are guaranteed to have been tested at the maker's works as specified in the Rules.
The foregoing is a correct description.

DAVIE SHIPBUILDING & REPAIRING CO. LTD.

Alex. C. Campbell
NAVAL ARCHITECT

Electrical Engineers.

Date Oct 3rd 1942

COMPASSES.

Minimum distance between electric generators or motors and standard compass 73'-0"

Minimum distance between electric generators or motors and steering compass 65'-0"

The nearest cables to the compasses are as follows:—

A cable carrying 2 Ampères 10'0" feet from standard compass 7'0" feet from steering compass.

A cable carrying 3 Ampères 12'0" feet from standard compass 8'0" feet from steering compass.

A cable carrying 1 Ampères 4'0" feet from standard compass 4'0" feet from steering compass.

Have the compasses been adjusted with and without the electric installation at work at full power Yes

Has the effect of switching on and off circuits, motors and other electro-magnetic apparatus within the vicinity of the compasses been noted Yes

The maximum deviation due to electric currents was found to be 1° E degrees on N.E. course in the case of the standard compass, and 1° E degrees on S.W. course in the case of the steering compass.

DAVIE SHIPBUILDING & REPAIRING CO. LTD.

Alex. C. Campbell
NAVAL ARCHITECT

Builder's Signature.

Date Oct 3rd 1942

Is this installation a duplicate of a previous case Yes If so, state name of vessel S.S. "FORT TADOUSSAC"
S.S. "PRINCE ALBERT PARK"

Plans. Are approved plans forwarded herewith - If not, state date of approval 21.8.41

Certificates. Are certificates of test for motors engaged on essential services and generators forwarded herewith Yes

General Remarks (State quality of workmanship, whether insulation tests, etc., have been made, opinions as to class, etc.)

The electrical equipment of this vessel has been fitted on board under Special Survey and in accordance with the approved plans and tested under full working conditions and found satisfactory.

The materials and workmanship are good and sound.

Noted
L.H.
11/1/43

Total Capacity of Generators 30 Kilowatts.

The amount of Fee ... \$ 125⁰⁰ : When applied for, Nov 16 1942
Travelling Expenses (if any) £ : : When received, 19

D. Halkett

Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUE 12 JAN 1943

Assigned See Insl. JE 5750