

Im.5.25.

30 AUG 1928

3

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *M. W. S. Topeka*

Rpt. *Haw*

No. *18213*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.

Nature of Survey *1st* S.S. No. *1* AND DAMAGE

Damage through *Grounding*

now repaired as follows:-

*See Bal Rpt 4319
Haw 17787*

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....	<i>3</i>						
Faired or repaired in place.....		<i>4</i>					

Other items:-

Vessel placed in 2nd dock & minor repairs effected.

The *1st* S.S. No. *1* has also been held and following repairs done due to wear and tear:- *Bottom Secured*

It is submitted the vessel is worthy to remain classed with record of Survey *7.28* and notation of *See Kel Nos. 28* as recommended.

*100 A.1
With prev
7.28 Kel
See Kel Nos. 28*

*Without special condition
Without etc*



Lloyd's Register Foundation