

"EMMY"

It is submitted before this case receives the consideration of the Committee, the London Surveyors be requested to state whether:-

- (1). The leakage in bottom plating as per St.J. N.B. Report 80, has been permanently repaired as recommended. ✓
- (2) The lifeboat davit has been faired, as per St.J. N.F.L. Report 2035.
- (3) The bolt in shell plating (s.s) in way of chain locker has been replaced by a rivet as per Hfx. N.S. Report 3949.



© 2019

27.5.42.