


of "Skard."

Nia Rpt. 1436.

It is submitted that the Christiania Surveyors should be requested to state whether a spare set of coupling bolts has been placed on board, also ~~whether~~ the dates when the fitting of the sea connections, stern tube, screw shaft & propeller were examined, as no mention of these is made in their report.

Ln. - 17/3/15

W280-0068



© 2020

Lloyd's Register
Foundation