

1

W282-0083

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Se Sk "GRETASTON"

Report Lrk

No. 18164

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

First Entry.

When due

+ 100A.1. (Steel)

2 SKs (Stl)

Cell DB. 343' 1120t, D.T.a 30' 860t, A.P.T 102t.

F.K. "Intermediate Green SK built in after hold dispensed with.

5 B.H. to upper SK, 1 B.H. to 2<sup>nd</sup> SK only. (Bulkhead letter from annex attached)

Cen. Lloyds ACP, P 38', B 119', F 43'

Lrk 22/2/24

The Surveyor should be requested to forward a copy of midship section of vessel as built, the number of strakes repaired, not agreeing with section forwarded.

2020  
Lloyd's Register  
Foundation