

CAPE PASSARO

REPORT OF TOTAL LOSS,

Vessel **HULL**

No. **50266**
Last Survey **24. 8. 1939**

No. **55933** in R. B. Wreck Book, p. **74/40**

Date of writing

State Type of Erections **RAIL & UNALIGNED**

Vessel's Name **Steel Stm. Trawler Cape Passaro** of **No**

Built at **SELBY.**

Built at **Selby** When **1939** **9** Casualty notice sent to **175.0**

Launched **19TH JUNE 1939.** Yard No. **1204**

Owner's Name **Hudson Stm. Fishing Ltd, Hudson Bros. Trs.** **30.0**

Builders **COCHRANE & SONS LTD.**

Address **St. Andrew's Dock, Hull.** **16.0**

Owners **HUDSON STEAM FISHING CO. LTD.**

Case previously before
Classing Committee.

Date

Particulars of Classification.

+100 A1 **+LMC** **8050**

Last Minute

Stm Trawler **9.3**

8.39 **CL** **10.9**

Managers

(Where necessary to be entered in Reg. Book.)

Residence **ST. ANDREWS DOCK. HULL.**

Port of Registry **HULL.**

Date of Casualty **May, 1940,**

Précis of particulars of Casualty **Admiralty announce lost by enemy**

If surveyed while building, afloat, or in dry dock

WHILE BUILDING AND AFLOAT.

air no. 114 to contain a
to bring out clearly any
presented in the endor

M AND BEAMS.

INCHES IN SHIP.

Any Departure from
Approved Plans to
be Noted.

et Floors, Frame

Reversed Frame

Vertical Struts

der, depth and thickness amidships

top Angles

bottom Angles

rs, No. each side and thickness

te depth (excl. of flange) and
thickness

Vertical Angle to Tank side

Bracket abaft $\frac{1}{2}$ len. from

stem

Vertical Angle to Tank side

Bracket

Suggested Record

Date of Committee

Committee's Minute

OMITTED FROM R.B.

TUE JUL 1940

OMITTED FROM R.B.