

Chief Surveyors

Received from Chief Surveyors

EL'S NAME Twn.Sc.M.V. "PRINCESS VICTORIA" Report Gls. No. 61311

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey FIRST ENTRY. When due

⊗A- "With Freeboard", "For Irish Channel Service"

2 Dks.

Tanks in way of tunnels 133t, DTf 14' 8lt, FPT 21t, APT 119t.

FK, 8BH., cem.,

B. & F. 286'

O.L. 322.8'

E.S.D.

*[Handwritten signature]*  
18.7.39 *[Handwritten initials]*

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register Foundation

W285-0112

Lojls.

& Classe for Wife:



© 2021

Lloyd's Register  
Foundation