



Lloyd's Register of Shipping,

I, Anton Graffstrasse,

Winterthur, 17th May, 1938.

RECEIVED
19 MAY 1938
Ans. *ack ro*
LONDON

Reference

E.

Dear Sir,

Messrs. Wm. Denny & Bros., Dumbarton,
Eng. Nos. 23335 and 23342.

With further reference to your letters of 3rd and 9th instant and mine of 5th instant, I have to state that I have despatched to the Sheffield Surveyors copy of Messrs. Sulzer Bros. advice of order for the crankshaft for Eng No. 23342.

It now transpires that the crankshaft for Eng No. 23335, stated in your letters as having been ordered by Messrs. Denny & Bros. from Messrs. Sulzer Bros. (London), will not be ordered from the Steelworks by Messrs. Sulzer Bros., Winterthur. It is not known here whether Messrs. Denny & Bros. or Messrs. Sulzer Bros. (London) have ordered this shaft and, therefore, no advice of order can be forwarded from this office to the Surveyors concerned.

The two crankshafts will be despatched from the Steelworks in England to Winterthur for finish machining, and that for Eng. No. 23335 will then be sent to Messrs. Denny & Bros., Dumbarton, who are building the engine.

I am, Dear Sir,
Yours faithfully,

J. N. Buchanan

The Secretary,
LONDON.

Lloyd's Register
Foundation

Referred to the Chief Engineer

19 MAY 1938

With

Admiral Glasgow

19/5/38

Memorandum to the Chief Engineer

RE: THE PROPOSED REPAIRS TO THE

RECEIVED

888 JAN 21 -
MOWDOX

© 2021

Lloyd's Register
Foundation

