



LLOYD'S REGISTER
23 AUG 1938
Ansd. 7/5
LONDON

Lloyd's Register of Shipping.

Royal Bank Buildings,
28, Constitution Street,

Leith, 22nd August, 1938.
Edinburgh, 6.

Reference

E

Enclos.


Dear Sir,

Wm. Denny & Bros. Ltd.
Yard No. 1333 - Eng. No. 1083.

With reference to your letter of the 17th instant regarding the above, we enclose herewith a letter which we have now received from Messrs. Laidlaw Drew & Co. Ltd., following an interview which the writer had with them at which the points raised in your letter were discussed. You will note from it what the makers now propose to do.

In reply to the last paragraph of your letter regarding the nature and duration of the tests witnessed by us, we have to inform you that the shop boiler to which the apparatus is fitted is a small and quick steaming one, and therefore the fall in the water level is fairly rapid. The apparatus is adjusted to cut in and start the pump when the water reaches a predetermined level, and to cut out when the water level is again brought up to the desired working level.

This occurred twice in the ten minutes or so during which the writer was standing by, and as the operation is purely/



© 2021

Lloyd's Register
Foundation

W285-0317(112)

Wm. Denny & Bros. Ltd.
Yard No. 1333 - Eng. No. 1082.

purely electrical the cutting in and out was instantaneous.

We are, Dear Sir,


Yours faithfully,

THE SURVEYORS.

Per.

John Houston

The Secretary,
LONDON.




© 2021

Lloyd's Register
Foundation

W285-0317(212)

Referred to the Chief Engineer Surveyor

23 AUG 1938



Handwritten notes in blue ink:
1st
2nd
3rd
4th
5th
6th
7th
8th
9th
10th
11th
12th



© 2021

Lloyd's Register
Foundation