

COPY.


WGW 28 CALCUTTA 67 19 WP.

DLT BARCLAY WHITEINCH.

VISITED TAIREA EARLY MORNING WENT OVER TWO
OIL TANKS BEFORE LLOYDS SURVEYORS ARRIVED BOTH
ENGINEERS FOUND STRINGER ^{choke} CHOKE RIVETS AND FRAME
RIVETS IN LOCALITY STRAINED WITH SURVEYORS WENT INTO
THREE TANKS THEY WERE DITTO SHELL STRINGERS DECIDEDLY
WEAK SOME MARGIN CONNECTIONS ALSO STRAINED CONSIDER
BOILER SEATS COMPLAINT TRIFLING NEXT WEEK FURTHER
EXAMINATION LETTER FOLLOWING OTHER COMPLAINTS EXAGGERATED
STAYING HERE ANOTHER WEEK TAKLIWA SAILED.

COOPER.

W288-0194



Lloyd's Register
Foundation