

COPY.

FREEBOARDS

(10.9.25)

CALCUTTA

HOUSTON BOMBAY INSTRUCTED JOIN YOU IMMEDIATELY SURVEY
TAIREA AND TAKLIWA AND CABLE FULLY JOINT REPORT EXPLAINING
WHETHER STATED DEFECTS IN DOUBLE BOTTOM AND BUNKERS
NECESSITATE DRYDOCKING AND FOR HOW LONG IN CALCUTTA OR
HOME PORT STOP DO NOT RENDER ACCOUNT MEANTIME

COMMITTEE



© 2019

Lloyd's Register
Foundation