

W. Beardmore & Co. Eng 606.

Sls. 43838.

It is submitted the Glasgow Surveyors
should be requested to state how the joints
of the liner on the screw shaft are made.

W.D.

17/7/84.

W289-0128