

26  
Sen's No. 230. I beg to forward a letter which has been re-

S.S. "DYNAMO".

It is submitted the Barrow Surveyors should be requested to state definitely if they are of opinion that the vessel may be recommended for classification subject to a hole being drilled through the margin angle, and <sup>a</sup> ~~the~~ rivet fitted through the hole in the outside plating and the margin angle, at the first dry-docking, or if they consider that the classification of the ship and the issue of certificates should be deferred until this rivet has been fitted.

Les. 13<sup>th</sup> & 14<sup>th</sup>/4/20.  
Ans. 15<sup>th</sup>.

© 2018  
Lloyd's Register  
Foundation  
15.4.20

Yours faithfully

W29-0025