

Stad Alkmaar

Ans. 15-908.

It is submitted the Surveyors be requested to confirm whether the diameter of the rivet-holes in the longitudinal seams of the boilers is 32 mm. as the approved plan shows it to be 35 mm.

Also according to the plan the thickness of the crank web parallel to the axis is 240 mm.



© 2019

2-1/2 3/4/40.

Lloyd's Register
Foundation

W290-0010