

Im, 12.30.

nt to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Stl. J. S. S. ALAUNIA

Report

Gls.

No. 44840

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

ature of Survey

1st Entry

When due


✠ 100 A. 1 (steel) Shelter deck with seaboard.
2. dks. (stl) & Shelter dk (stl - ws) 3rd dk (stl) with 1.2.3 holds
F.K. 11 BH (10 BH to shelter dk. 1 BH to upper dk)

Cell DB 447' 1937t DT of 51' 1470t. FPT 106. APT 47t

B & F on shelter dk 435' Cmn. Lloyds A & C.P

WKM
16.7.75

It is concluded that the seam of the strake below "B" deck sheer strake is double rivetted and not single as stated in the report; but the Surveyor should be requested to state if this is so.




© 2021

Lloyd's Register
Foundation

W293-0028