

Hellsund

The original screw & intermediate shafts have been retained with the new oil engine.

Have these shafts been approved?

If not, are they suitable for the new engine?

BA

28/1/40

© 2019

Lloyd's Register
Foundation

W295-0160