

Subject to the bow-plates of A' Shalke each side,
repaired by E. W. 33. Being reviewed at the next dry
docking.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

17 JUN 1937

NAME

"HELLESUND"

Rpt.

Clot

No. 4937

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

f Survey

It is submitted before this case receives the
consideration of the Committee, the Surveyors be
requested to state whether the bow plates of A Shalke,
as above, or S.R.L, have been dealt with

No. See letter 22/6/37

15.6.37

Att



© 2019

Lloyd's Register
Foundation

W295-0187