

L.T.W. Henderson & Co
Box No 901

Plates Nos B674 + B675 cut too small
at steel works and returned.

Replaced by 2 @ No 935C

L.C. Davis



5-3-30 © 2020

Lloyd's Register
Foundation

W3-0089