

17 APR 1946

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "BALTEAKO"..... REPORT Lon. No. 113645

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A General Examination becomes due 11.46.

The class is subject to permanent repairs to indented shell plating etc. (p & s) and to boat deck planking etc. at the first convenient opportunity and to (a spare bower anchor being repaired and retested).

The LONDON Surveyors report the vessel placed in dry dock, bottom coated and minor repairs effected.

Temporary bunker in No.2 upper tween deck now removed and openings in tween deck bulkhead closed with steel plates.

It is submitted the vessel is worthy to remain as classed with record of docking survey 2.46 subject as above.

2.46 Lon. subject.



© 2020

1.7.46
5.4.46
Lloyd's Register
Foundation

W300-0045