

1

"How Empire Seacock"

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S.S. "BELLHAVEN"

Report N.Yk

No. 17618.

## For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due


The Downers Pump has been dispensed with for the present.  
Chain Cables of Cast Steel, fitted as required.

❖ 100 A.1. (steel) "Shelter Dk. with Freeboard"

1 Dk. (steel) and Shelter Dk. (steel) & Webframes. "Longitudinal Framing"  
Call DB 351' 1512t. FPT 187t. APT 175t.

FK. 7BH to Shelter Dk. 1st. am. A9CP.

P 45', B 110', F 38' on Shelter Dk.



© 2020

2-12-19

Lloyd's Register  
Foundation

W301-0077