

Motor Yacht. "Crusader."

Sou 13447.

Before this case receives consideration the Southampton

Surveyors should be requested to answer the following

numbered questions by wire:-

1. What is the smallest diameter of the tube shaft?
2. Is the tube shaft fitted with continuous liner?
3. If the tube shaft does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive?
4. Is the sea suction provided with an efficient strainer which can be cleared within the vessel?
5. If a donkey or heating boiler is fitted is the boiler used exclusively for domestic purposes and what is the heating surface?

With regard to the latter question it should be pointed out that the plan of pumping arrangements shows a space marked "Boiler room". If a boiler is fitted, a plan should be submitted for consideration.

Q.R.R. *B.H.*

20.2.29.



© 2020

Lloyd's Register
Foundation

W306-0033