

Holds, &c.

Direct Suctions to the Engine Room Bilges, No. and size

lines

No.

Made by

Sulzer Bros.

Campbell & Nicholson's Jar No 361

Winterthur

Report No.

91

It is submitted that this Report be ~~returned~~ ^{sent} to the *Sou.* Surveyors for their guidance and for completion.



Date

20.20

17/12/28

Lloyd's Register Foundation

W306-0053

the internal surfaces of the receivers be examined here a drain arrangement fitted at the lowest part of each receiver

Yes