

35 APR 1946

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "BRITISH LADY" REPORT Lth. No. 21601

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

This vessel has the notation of "Examined (Mod.) 6.45" valid for 12 months and the notation "Oil Storage Vessel" inserted in the Register Book.

The LEITH Surveyor reports examination of vessel afloat to ascertain the vessel's suitability to proceed from Rosyth to the River Tyne. It was noted that a sheerstrake plate in way of No.4 summer tank (s.s.) had fractured and a cement box had been fitted. This temporary repair, they report, is considered efficient meantime, but recommend that permanent repairs be carried out at the first opportunity.

It is reported the vessel arrived in the River Tyne on the 28th March last.

It is submitted that action be deferred for a short period for further advise upon the vessel.

D.



15/4.46.  
2000

Lloyd's Register  
Foundation

W306-0103