

1E

1m.11.35.

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Campesador II

Rpt.

W. H. H. H.

No. 5-9875

7272

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Type of Engine 2 Oil Engines 4 S.C.S.A.
each 16 1/2 Cy. 6"-7"

~~If Boilers fitted with forced draught~~

Tail Shaft: If fitted with a continuous liner

If fitted with an outside gland of approved type

No. Bronze Shaft

Yes

(B for Reg. Bk.)

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + LMC 8.38

W. H. H. H.
16/9/38.

The N.Y. Surveyor should be requested to forward the See ply to Jones 27/9/38
test certificates for the dynamos & motors.
Lloyd's Register Foundation

Main Air Compressors. No. 2 each Imp. No. of stages 1 Diameters 6" Stroke 7" Driven by ...