

Messrs. Philip & Sons

Yacht No. 847

It is submitted Messrs. Philip & Son be informed that the Society's fee for the special superintendence of the vessel during construction does not include the fees for testing steel plates, forgings, chain cable, &c. These fees are charged by the Society direct to the Manufacturers and are paid by the latter unless some special arrangement has been agreed upon between the Shipbuilders and the Manufacturers when the contract for the vessel was placed.

Ph. 20.12.37
Ans. 21.12.37
P.C. Phy.

Ph
21.12.37.



© 2019

Lloyd's Register
Foundation

W307-0105