

11.38.  
d the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

2 E

ived by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME Yt "ALASTOR".

Rpt.

Sou.

No.

17507.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS~~ FOR S.S. No. 3

This Survey, due 7,38 now held  
partly completed, and the following repairs carried out (due to

now

):-

It is submitted the vessel is eligible to remain as classed, with  
notation of ~~LMC~~ 7,39 as recommended.

W307-0180

1.9.39.

General Observations Opinion and Recommendation