

"AMULREE".

=====

GrO.38.

It is submitted before this case receives consideration, the Surveyor should be requested to endeavour to obtain full particulars of the air receivers.

The particulars required are thickness and tensile strength of the shell plating, whether welded, seamless or riveted. If riveted, particulars of the longitudinal joint should be given; also the figure of 1830 now given for the diameter should be confirmed, as this does not appear to be consistent with a capacity of 120 litres.

Further it is noted that the working pressure of receivers is given as 35 Kg/Cm², whereas the identification marks on the two receivers show a working pressure of 35 Kg/cm² for one and 30 Kg/cm² for the other.

The Surveyor should also be requested to furnish particulars of the 16 BHP Junkers auxiliary engine, viz:- number and diameter of cylinders, length of stroke, maximum pressure in the cylinders, span of bearings.

Lr 20/19

20.9.38.



Lloyd's Register
Foundation

W307-0214