

W309-0129

2 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

28 SEP 1939

EL'S NAME

Guards

Rpt.

Incl.

No. 50271

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey

COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 2

This Survey, due 6.39 now ~~partly~~ held

now

completed, and the following repairs carried out (due to wear & tear) :-

H.P. Cylinder rebored. & running repairs

It is submitted the vessel is eligible to remain as classed, with notation of + Linc. 9 39


S. 8 39

as recommended.

H. R.

28.9.39

© 2021



Lloyd's Register  
Foundation